



1-the tank leaks water through the level probe, the technician has disassembled the probe, filed down the area where it sits and reassembled it with a silicone gasket.