



we tried to place correctly and repair the remis in the driver's cabin, but it has been impossible.

the only possible option is to replace the driver's door Remis.