


2-the extension of the dining table is blocked,

the technician has disassembled the table to put the closing spring correctly. He has also adjusted the pressure of the screw that acts as a closure.



3-the refrigerator door touches the lower wood when opening,

The technician has removed the screws holding the fridge in place and lifted it up a bit at the front, then put a thick one under the front. Thus, it has been achieved that when the door is opened it does not touch the lower wood of the same structure.

