

Before delivering the vehicle to the customer, the technician saw that the roof did not close. touched from the front. The technician had to adjust the hinges and move the entire roof a little to the back so that it does not touch the front part and can be closed.