

1-the windscreen remis, on the left side , is not correctly positioned on the upper guide, there are several holes without passing through the rod. the tencio has partially removed the Remis to be able to correctly insert the rod and pass through all the holes.



2-the belt protectors that go on the sofa are loose. The technician has had to disassemble them, clean the area and glue them again with stronger glue.



3-the rear cupboard above the bed cannot be closed. the tencico has had to adjust the closure and the hinges.

