

Globescout Plus- VF7YCBNFC12S15012 (OT8483-L2)

1. The customer complains that the right telescopic arms of the sliding door (entrance door) window worked extremely hard.

After checking the 2 telescopic arms, the technician has had to replace **ONLY the right side** one, the other worked correctly.

Unfortunately I had no pictures of the telescopic in place, sorry, just one of the defective arm the technician has given me

