

1-the front remis was out of place on the left side, and crumpled, the technician had to completely disassemble it, put it in place, fixed it and put it all back together

2-the cover of the floor box under the seat is wavy. it must be replaced.I could not find the reference in the spare parts program.