

As reported in the delivery review, the base of the pop-up roof does not fit well and has a lot of separation distance.

There is a rubber band incorrectly placed to hide it, the technician has unhooked the joint, cleaned all the glue and placed the joint correctly, filling in the parts that had a difference in level so that it looks watertight.

Within the working time, material such as black sikaflex, cleaning material, polishing is included.

