Globescout Plus- VF7YCBNFC12S15012 (OT7699-8483)

1. The customer complaints that the water pump has stopped working. After checkings the technician has had to replace the pump