



1-the safety belts of the rear seats are locked, the technician has had to remove the belts, to be able to move a few millimeters so that they work straight, mount and test.