

Before delivering the vehicle to the customer, the mechanic has seen that the gray water tank has a leak. He has disassembled the drain tap, has put a new gasket and has reassembled it. later it has proven that it will not leak anymore.