


ROADCAR 601- VF7YCBPFC12U33938-OT7490

The customer complains that the fresh water tank leaks for the red cap this time. The technician has had to adjust the cap by sanding a little bit the mouth in order to adjust the cap correctly. and refill tank several times to check it



The customer complains that the combicassette from dinningroom is not centered. After checking the technician has noticed that the combicassete is 11,5 cms in lower area and 12 cms in upper area in comparison to the wall which makes it to look not straight. The technician has dismantled it and has centered it, and refixed again straightly. Also the same problem in the Toilet, sorry, in this last case I have not got the measurements specifically.



The customer also complains that the toilet tap which is also a shower tap does not work correctly. The hot water does not activate the water pump only the cold water. The technician has had to replace the tap because it is not a correct function, the switch fails

