

The customer complained that every time it rained or cleaned the outside of the vehicle, water entered for the rear righth window, the technician has checked and water enters through the window gasket. The technician has disassembled the complete window. He has cleaned the area and has reassembled the window with a new thermostat gasket. After you have checked that no water enters.