

1-The sliding door window blind is blocked, the customer cannot open it.

the technician has partially disassembled it, has greased and adjusted the closures and has repositioned the shutter.

then it has tested the correct operation.

2-the fresh water tank leaks, the technician has removed the drain rod from the tank, and has repositioned it since it did not seal well. He has put it on correctly and afterwards he has tested that it will not leak anymore.