

Globescout Plus- VF7YCBNFC12S15012 (OT6009)

1. The customer complaints that kitchen down drawer gets stucked and sometimes cannot be opened.

After checking, the technician had only to readjust the drawer and at the beginning it seem that the lock was defective but it worked correctly



2. The customer complaint that the upper kitchen cupboard door does not close correctly.

After checking the technician had to dismount them and refixed and adjust the door correctly.



3. The customer also complains that the door of the rear cupboard does not close correctly and gets opened while driving. The technician had to dismount and readjust the lock



4. The customer complains that the water tank probe only marks 75%.

The technician has checked it and it was clean and seemed correct. He checked if there was any problem with the connection and he has noticed that it had become not well connected in one area. He has connected again and it worked correctly.



