

Outer toilet cassette door cannot be opened, technician has forced the door to open and adjusted latches with frame. after the operation has verified that it has been adequate.